


SLW-7702-1.5 (CDS0250-274-0-CYL) Two Handle Widespread Lavatory Faucet Installation Guide



installation duide		
Model Numbers	Specification	
☐ SLW-7702-1.5 Two Handle Widespread Lavatory Faucet	Two Handle Widespread Lavatory Faucet featuring 8"-16" mounting configuration shall include ceramic cartridges, copper supply lines, 1/2" IPS inlet connections and 1.5 gpm (5.7 L/min) aerator. Faucet shall be made from metal construction, plated in standard polished chrome finish.	
Modifications		
☐ -1.0 CG 1.0 gpm (3.8 L/min) flow restrictor		
Note: Append appropriate -suffix to model number.		
Warranty		
Limited Lifetime - to the original end purchaser in consumer/residential installations.  5 Years - for industrial/commercial installations. Refer to www.symmons.com/warranty for complete warranty information.	E	


## **Dimensions**



Measurements			
Α	8", 203 mm		
В	11-5/8", 295 mm		
С	2-5/8", 67 mm		
D	Deck Thickness Ref.		
	Max. 1-1/4", 32 mm		
Е	Hole Size		
	Max. Ø 1-1/2", 38 mm		
F	6-1/2", 165 mm		
G	To Backsplash		
	Min. 2-1/2", 64 mm		
Н	6-3/4", 171 mm		
Ī	1/2-14 NPSM		

Note: Dimensions subject to change without notice.

## **Parts Breakdown**



Replacement Parts				
Item	Description	on	Part Number	
Α	1.5 Aerator		RL-039-1.5	
	1.0 Aerato	or	FLR-109-1.0	
С	Handle			
D	Set Screv	V	RL-058	
E	Flange			
F	Washer			
G	Metal Wash		RL-187	
Н	Mounting N			
I	Mounting Sci	rews		
J	Cold Cartric	lge	KN-113	
K	Hot Cartridge		KN-114	
Tools Required for Installation				
Adjus	table Wrench		(Name of the Control	
Allen Wrench:				
Handle (2 mm)				
Spout (1.5 mm)				
Phillips Head				
Screwdriver				
Ocicwanie				
Plumber Putty				
Plumber Tape				
			<b>/</b>	
Silicone				
			U	

## **Notes:**

- 1) Align set screw (B) with pin hole in centerbody for rigid spout (see FIGURE 1).
- 2) Apply a bead of silicone around the perimeter of trim installed flush to sink.
- 3) Apply plumber tape to all threaded connections.

▲ WARNING: This product can expose you to chemicals including lead, which is known to the state of California to cause cancer, birth defects, or other reproductive harm. For more information, go to: www.P65Warnings.ca.gov.